

Presby Onsite Wastewater Treatment System Inspection and Evaluation

Advanced Enviro-Septic[®], Enviro-Septic[®], Simple-Septic[®] and EnviroFin[™] Passive Wastewater Treatment and Dispersal Systems


Dennis Fogg, Don Prince, Mark Vander-Heyden Presby Technical Team

Presby Environmental

2016
































12


- All systems require two vents (high and low)
- Gravity system's roof stack is high vent, low vent at field
- Pumped systems require Bypass Venting or High Vent
- Low vent opening 3' min. above final grade
- Vent diameter is 4", (multiple or 6" dia. for large systems)
- Schedule 40 or equivalent PVC pipe for all vent stacks
- Recommend all vent joints be glued or equivalent
- Charcoal filters are never recommended
- Efficient filters block passive air flow to the roof vent and should not be used




















































































































































System Sand

From Inspection Report

3. System Sand – The System Sand appeared black between the pipes at a horizontal depth of 6-12 inches indicating anaerobic (without oxygen) conditions were still present within the bed four full days after opening the ends of the bed. Samples of the System Sand were taken from locations at each end the bed and a third-party sieve analysis was conducted. The results of the testing showed that the sample did not pass the specification for System Sand. The sieve analysis indicated a fines content (any material passing the #200 / 0.075 mm - sieve) of 5.2% by weight. The specification for System Sand in the Presby NH Design and Installation manual states a fines content of not more that 3% by weight (see sieve analysis below). Areas of the bed were lacking the correct amount of System Sand over the pipes (6 inches) and in some areas lacked sufficient cover as well (see pictures below).

From Inspection Report (Recommendations):

9. System Sand – An insufficient amount of System Sand above the ES pipes, while not considered a major contributing factor to the failing conditions of his system, may have contributed to the breakout due to lack of cover in that area. It also may have inhibited air flow in parts of the field where a lack of System Sand allowed loam cover material to be located in close proximity to the top of the pipe. The specification for the amount of System Sand is 6 inches above the pipes, which should be present for proper function of the system.

Although the System Sand in this bed contains fines above the Presby specification (3% of the sample by weight), at 5.2%, the fines are not considered to impact the performance of the system to a significant degree and certainly any improvement would be so small as to not justify replacement of the existing System Sand.

Recommendations

- Recommend Rejuvenation
- Increasing Amount of System Sand & Cover in Areas Where it Was Lacking
- Removal of Effluent Filter
- Creating Surface Water Diversion Upslope from the System

Error Ingoartion Banat

Recommendations:

8. Rejuvenation – The evidence seems to indicate that insufficient sertic tank maintenance, a clogged effluent filter, lack of oxygen (anaerobic conditions) and heavy organic loading to the field were the main causes of failing conditions and effluent breakout experienced with your Enviro-Septic system. Since these root causes are capable of being eliminated, your system is a good candidate for the rejuvenation process. Rejuvenation re-establishes acrobic (with oxygen) conditions within the Enviro-Septic Pipes and System Sand by draining and allowing the field to rest for at least 72 hours (see Rejuvenation procedure in the Presby NII Design & Installation manual).

72







